

## Restores Stainless steel Lanai railing in Hawaii

Six months after installation, unsightly rust stained 316 Stainless steel support posts on railing ruins pristine appearance of \$25,000.00 installation at a Hawaiian estate.



Close-up photos of support posts show unsightly pitting and staining.

High strength 316 grade Stainless steel is susceptible to rusting.

Warm, damp environments accelerate the damage.





Support post pictured on left has been cleaned of rust stains with EcoSeal Calci-cure, rinsed, dried and sealed with EcoSeal Fortify.

The guard rail shown at right will maintain the "like new" appearance as the Fortify sealed post for many years once cleaned and sealed.

Stainless installations from Massachusetts to Texas have stayed "like new" for more than 5 years after cleaning and protecting with EcoSeal Fortify

